



NTSB National Transportation Safety Board

**Circuit City Cessna 560
Pueblo, CO
February 16, 2005**


Dr. Daniel Bower
Aircraft Performance

Overview

- Types of icing environments- SLD
- Accident aircraft performance
- Cessna 560 modified stall warning system
- De-ice boot activation
- Automatic mode for de-ice boots
- Previous icing recommendations

Part 25 Appendix C

Continuous Maximum




Effect of SLD on ice accretion

Wing leading edge cross section




Resultant Ice Shapes



Front Edge of Wing

Rough Ice

Altitude Time History



Accident Airplane Relevant Speeds



Accident Sequence

- Airplane slowed below V_{approach}
- De-ice boots not operated in second icing layer
- Presence of an estimated $1/6$ of an inch or less of ice accreted in SLD conditions caused the airplane to stall prior to stick shaker
- Airplane entered a rapid left roll
- Airplane did not recover in the 1,500 feet agl available

Stall Warning modifications

- 1996 - In response to 3 accidents in icing conditions FAA performed flight testing with artificial 1/2-inch ice shapes.
 - Ice Shape generated using one App C condition
 - Larger droplets not considered
- Resulted in modifications to stall warning system to increase stick shaker speed in icing conditions

De-ice Boot Operation

- 1998 – NTSB issued Rec. A-98-91 to activate deice boots upon entering icing conditions
- FAA issued NPRM for several airplanes including the 560.
- Cessna used results from 1996 flight tests with 1/2-inch ice shape to request withdrawal of NPRM
- FAA withdrew NPRM

De-ice Boot Operation

- Current company and manufacturer guidance states boots should be operated when ice is 1/4- to 1/2-inch thick, and AFM states
 - “early activation of the boots may result in ice bridging on the wing”
- Deice Boot Bridging – Ice in the shape of an inflated deice boot forms as the boot is cycled, which cannot be removed by subsequent cycles

De-Ice Boot Bridging - Recent research

- 1997 Deice Boot Bridging Workshop
- FAA AC 25.1419 (2004)
- Recent research by FAA

No evidence that modern turbine powered airplanes are at risk for bridging

Total number of accidents investigated by the Board related to bridging = **0**

Automatic boot cycle

- Bridging is no longer a valid reason to allow a buildup between boot cycles
- Research by FAA indicates residual ice is not as detrimental as intercycle ice
- Manually operated boots can lead to excessive intercycle ice buildup in high workload situations

Revised Icing Certification

- Upgrade aircraft icing certification criteria to include SLD **(A-96-54)**
- Research into effects of in-flight icing, including intercycle and residual ice **(A-98-92)**
- All de-ice boot aircraft certified for icing should be subject to revised icing criteria

Summary

- **Airplane slowed below approach speed**
- **Deice boots were not operated during approach**
- **Airplane encountered supercooled large droplets**
 - Caused a thin, rough ice accretion with large aerodynamic penalties
- **Stall warning was inadequate**
 - Ice accretions used to determine the stall warning margin were not representative of the most detrimental

Summary

- **Deice Boots bridging is not a concern**
 - Warrants activation of deice boots upon entering icing conditions
 - Warrants development of system for automatically cycling of deice boots
- **Icing certification standards**
 - Need to be updated based on accident history and recent research, and applied to all deice boot equipped aircraft



NTSB