



International Investigations


Global Collaboration with Domestic Impact

Materials Laboratory

Michael Budinski

Materials Laboratory: International Overview

- Technical specialists:
 - Materials science
 - Metallurgy
 - Fire science
- Laboratory
 - Material failure analysis
 - Structural analysis
 - Group examinations
 - Experimental testing
 - On-scene examinations
 - Consultation




NTSB National
Transportation
Safety Board



Materials Laboratory: International Overview

12-month “snap shot” of
Materials Laboratory work based on labor hours



NTSB

National
Transportation
Safety Board



El Al Flight 027, Boeing 777-200, Tel Aviv, Israel

- Normal takeoff from Ben Gurion International Airport—the left main landing gear (MLG) did not retract
- Aircraft returned to airport and landed without incident



NTSB

National
Transportation
Safety Board



El Al Flight 027, Boeing 777-200, Tel Aviv, Israel

- Post-flight inspection revealed fractured left MLG forward trunnion




NTSB National
Transportation
Safety Board



El Al Flight 027, Boeing 777-200, Tel Aviv, Israel

- Metallurgical analysis of the fractures, materials and specialized crack inspection
- Failure from fatigue at grinding burn cracks
- Examination of MLG steps at the overhaul shop in Singapore
- Opportunities identified to lower the probability of recurrence



NTSB National
Transportation
Safety Board



Copterline Oy, Sikorsky S-76C, Tallinn Bay, Estonia

- Copterline Sikorsky S-76C+ helicopter (OH-HCI Finland), crashed into the Baltic Sea shortly after takeoff from Tallinn, Estonia
- The investigation revealed the failure of the forward main rotor actuator




NTSB

National
Transportation
Safety Board



Copterline Oy, Sikorsky S-76C, Tallinn Bay, Estonia

The NTSB conducted a metallurgical evaluation of the main rotor forward actuator components, exemplar actuator pistons, and other system components



NTSB


National
Transportation
Safety Board



Copterline Oy, Sikorsky S-76C, Tallinn Bay, Estonia

Metallurgical evaluation revealed failure of the coating system on the actuator pistons

- Excessive wear of components
- Hydraulic fluid leakage
- Blockage of a fluid return port



NTSB

National
Transportation
Safety Board



Copterline Oy, Sikorsky S-76C, Tallinn Bay, Estonia

NTSB Safety Recommendations A-05-33 through -35 issued, which ask for:

- Immediate leakage testing of in-service actuators
- Visual and laboratory examination of hydraulic fluid filters
- Preflight check of flight control “stick jump” and control movement smoothness



NTSB

National
Transportation
Safety Board



UPS Flight 6, Boeing 747-400F, Dubai, UAE




- NTSB Materials Laboratory fire investigator on scene
- Developed a fire test program to understand cargo fires:
 - Quantify the fire load posed by lithium-ion batteries relative to ordinary combustibles
 - Quantify the size and growth rate of a cargo container fire



NTSB National
Transportation
Safety Board



Cargo Container Fire Experiment



NTSB National
Transportation
Safety Board



Cargo Container Fire Experiment



NTSB National
Transportation
Safety Board





NTSB | National
Transportation
Safety Board

