



VEH Photo #44 - Damaged Bearing Cage, Melted Bearings, and Grinding Marks on Bottom of Torque Plate on Right Side Tag-Axle Spindle