HWY-05-M-H035
Wilmer, Texas

ATTACHMENT #9

WABCO ABS ECU Printout

(4 pages)

MERITOR WABCO
Vehicle Control Systems

SAE Fault Code: SID 6
FMI 8

Description: Right Third Wheel Sensor Excessive Slip

The ABS ECU has detected a wheel slip condition of more than 16 seconds in duration. Adjust the air gap by pushing the sensor all the way till it touches the tooth wheel.

Sensor Installation

Meritor WABCO ABS Fault Report

VIN: 487
Date: 11/9/2005
Time: 1:11:27 PM
Page: 1

Fault #	Description	Status	SID	FMI	Count
1	Right 3rd Sensor - Slip	Inactive	6	8	1


My Documents
Shortcut to RollCall
My Computer
Calculator
My Network Places
APIChecker
Recycle Bin
WordPad
Internet Explorer
Meritor WABCO ...
Acrobat Reader 5.0
Windows Explorer
Shortcut to J1939_Diag
Shortcut (2) to J1939_Diag
Meritor WABCO ABS
Tractor ECU Display Component Tests ESC Menu Help
EXIT
ABS
ATC
ECU Information
ECU Type Frame (12V)
Configuration 6S/6M
Part Number 4461060700
Manufacture Date 05/1998
Serial Number 00000487
Software Rev. D153
Engine Data Link J1922
Wheel Sensor
RPM MPH
Left Front < 7 0
Right Front < 7 0
Left 2nd < 7 0
Right 2nd < 7 0
Left 3rd < 7 0
Right 3rd < 7 0
Faults
None Existing Yes Stored
Learned Components
ATC Valve
Retarder Relay
Data Link
Control Status
ABS Brake Off
ABS Retarder Off
ATC Brake
ATC Engine
Switches
ABS Off
ATC
Lamps
ABS ATC Trailer
Off N/A
Voltages
Diagonal 1 0.00
Diagonal 2 0.00
Battery 3276.75
Road Speed
127.5 (mph)
ATC N/A
11/9/2005
1:12 PM
Start
Meritor WABCO ABS
1:12 PM