HWY-05-M-H035
Wilmer, TX.

ATTACHMENT #22

Repair Order (unkown vendor) on 6/25/05

(2 pages)

1-800-820-3072

REPAIR ORDER

BUS 717

NAME	DATE
Global Limo	6-25-05

ADDRESS: 1708 North Jackson RD

MAKE	TYPE OR MODEL	YEAR	RECEIVED
MCI	G model	98	A.M. P.M.

SERIAL NO.	ENGINE NO.	PROMISED
	60 Series	A.M. P.M.

ODOMETER	LICENSE NO.	TERMS	PHONE WHEN READY
			☐ YES ☐ NO

OHAUT TX	ORDERED WITH	ENTRY	PHONE
	Raul G		

DSS	ISJ	LABOR CHARGE
Lubrication	☐	
Change Oil	☐	
Change Oil Filter Cart.	☐	
Change Trans.	☐	
Change Diff.	☐	
Pack Front Wheel Brgs.	☐	
Adjust Brakes	☐	
Rotate Tires	☐	
Wash Polish	☐	
State Inspection	☐	

MATERIAL USED

QTY.	PART NO.	DESCRIPTION	PRICE	AMOUNT
1	50 DU	Alternator	1060	00

NOTE: According to Drive Rosa Saldana, This was an en Route Repair (New Alternator) That was made near El Paso, TX.

NTSB

OUTSIDE REPAIRS

BROUGHT FORWARD

TOTAL PARTS

OPER NO.	INSTRUCTIONS	
	Customer Complain Battery Dead. Bus Shut Down. Drove to Location. Service Call Found Alternator Not Charging. Remove Batteries Installed Loaner Batt. Drove Bus to Shop R+R Alternator. Charged Customer Batteries 2 Hrs. 4 Hr Labor	1
	6 HRS. X 70.00 HRS	

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will include your estimate selection.
Tentative estimate: I understand that my car will be ready/available within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
2. Please proceed with repairs, but call me before continuing if the price will exceed $ _____
3. I do not want an estimate. _____

QTY.	ACCESSORY NO.	ACCESSORIES	PRICE	AMOUNT

TOTAL ACCESSORIES

GAS, OIL & GREASE	PINT
GNS. GAS	
GTD. OIL	
LBS. GREASE	

METHOD OF PAYMENT:		
☐ CASH	TOTAL LABOR	420 00
☐ CHECK	TOTAL PARTS	1060 00
☐ CHARGE	ACCESSORIES	
LABOR:	GAS, OIL & GREASE	
☐ FLAT RATE	OUTSIDE REPAIRS	
☐ HOURLY	TAX	
☐ BOTH	TOTAL AMOUNT	1480 00

Kardex GT3810/GT3811

FEB-15-2006 09:16 NTSB 015533 P.02/07