VEH Photo #58 - Underside of Left Side Drive Axle Rotor on Axle Hub (Source: Dallas County Sheriff's Dept.)