VEH Photo #61 - Outside View of First Axle Left Side Rotor Removed From Axle Hub (Source: Dallas County Sheriff's Dept.)