VEH Photo #64 - First Axle Left Side Outside Wheel Bearing Component Parts (Source: Dallas County Sheriff's Dept.)