

VEH Photo #59 - Right Side Drive-Axle Rotor Showing Transverse Cracks (Source: Dallas County Sheriff's Dept.)