



VEH Photo #14 - Close View of Broken Brake Carrier in Hand Hole (Source: Dallas County sheriff's Dept.)